

Greaves Road Analysis



WallacePancher Group completed a field analysis of approximately one mile of roadway in Washington County. Photographs and field notes were used in preparing an Engineering Analysis Report of the condition of the road. Specific elements noted in the report include roadway material, location condition of existing culverts and overall condition of the roadway.

The purpose of the report is to provide documentation of current road conditions for our client. Our client is in the process of developing a piece of property located on the road and wants to insure he is held responsible for repairs necessary related to his development only.

SERVICES PROVIDED:

- **Engineering Field Evaluation**
- **Roadway Analysis Report**